usda-forest service ndex file No. <u>G-//</u> r <u>5N</u> R. <u>38</u> E	CORNER RECORD (SEARCH) Tract or Cor. (Ref. FSM 7151.4) Survey No. No. No. County UMATILLA
Merid. WILL	N.F. <u>UMATILLA</u> State <u>OREGON</u>
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
T5N R38E	
1511 1302	
C¼ S9	
	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
·*	
	·
	6.
PHOTO IDENTIFICATION DATA	
Photo No	<u>-</u>
Filed At.	_
Object Ident	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
dent. By	-]
LANE COORDINATE POSITION DATA	$\frac{1}{\Lambda}$ –
State Zone	-
X	
T	-1
Estab. By	

CORNER RECORD (PERPETUATION)

Description of monument	and accessories	l established to perpetuate the
original location of this c	erner:	

At surveyed point set 1"x30" Galvanized Pipe with brass cap stamped:

Set cap 24" in ground with mound of stone to cap.

Bearing Trees:

Index File No.

A White Fir 16" dia. bears S240W 10.4 ft., scribed: C 1/4 S9 BT.

A White Fir 25" dia. bears \$890W 15.8 ft., scribed: C1/4 S9 BT.

Attached 54-3 and 54-4 signs to both BTs. Attached brass washers stamped LS 1294 to foot blaze of both BTs. Painted blazes and 6" band around both BTs red.

R.

Cartified Car. Resert Property Viet No. Filed At:

Tract

Bery: No.

M:

Cor.

T5N

R38E

1980

OR PLS 1294