## History of original corner establishment:

No corner was originally set.

DIAG	RAM
T5N	R38E
E	1 16
c—S	+c

Description of corner evidence found:

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 1"x30" Galvanized Pipe with 3" brass cap stamped:

Set pipe 22" in ground with mound of stone and dirt to cap.

New BTs:

A Spruce 11" dia. bears N22<sup>O</sup>E, 27.4 ft., scribed CE 1/16 S8 BT.

A Fir 6" dia. bears S49<sup>o</sup>E, 15.0 ft., scribed CE 1/16 S8 BT.

Attached 54-3 and 54-4 signs to both BTs. Attached brass washer stamped LS 1294 to foot blaze of both BTs. Painted blazes and 6" band around both BTs red.



 $C^{RDWN} \xrightarrow{ZELLER89} C^{RDWN} \xrightarrow{ZELLER89} C^{RDWN} \xrightarrow{T5N} R38E \xrightarrow{E \frac{1}{16}} C \xrightarrow{S 8} 1980$ PLS 1294

I hereby certify the above corner monument was established as herein described on October 29, 1980.

Witnesses: R. Orton A. Hanley

Office of County. Surveyor	County of Umatilla
State of Oregon / baraby continu	alian alian with the transferred and and a second
for record on the day of Decemb	y
David Moumber	y Betty Shatt.
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

☆ GPO-798-276