History of original corner establishment:

No corner was originally set.

DIAGRAM	1
T5N	R38E
SE $\frac{1}{16}$	<u>58</u>

Description of corner evidence found:

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 1"x30" Galvanized Pipe with 3" brass cap stamped:

Set pipe 24" in ground with mound of stone and dirt to cap.

New BTs:

A White Fir 12" dia. bears N30°E, 78.3 ft., scribed SE 1/16 S8 BT.

A White Fir 14" dia. bears S40°E, 49.1 ft., scribed SE 1/16 S8 BT.

Attached 54-3 and 54-4 signs to both BTs. Attached brass washer stamped LS 1294 to foot blaze of both BTs. Painted blazes and 6" band around both BTs red.



I hereby certify the above corner monument was established as herein described on October 29, 1980.

Witnesses: R. Orton A. Hanley

Office of County Surveyor	County of
State of Oregon / hereby certify the	t the within instrument was filed in this office
tor record on the day of December Daniel Prumber by	
David Prunbern by.	Betty Shatte
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

\$ GPO-798-276



CROWN ZELLERBA

R38E

S8

T5N

SE