History of original corner establishment:

No corner was originally set.

iuex	File	No.	H-9a
DIA	GRAM		
T5N	R3	8E	
s	6		
S 8	3		

Description of corner evidence found:

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set a 1"x30" pipe with a 3" brass cap stamped:

Set corner 24" in ground. No stones for mound.

From which:

A White Fir 12" dia. bears $\rm S25^0W$ 20.0 ft., scribed: S 1/16 S8 BT.

A White Fir 18" dia. bears $\rm N55^0W$ 31.8 ft., scribed: S 1/16 S8 BT.

Attached 54-3 and 54-4 signs to both BTs. Attached brass washer stamped LS 1294 to foot blaze of both BTs. Painted blazes and 6" band around both BTs red.



CROWN Z	R38E
CPC T5N	R38E
$S\frac{1}{16}$	1
\$8	1
OR PLS	1294

I hereby certify the above corner monument was established as herein described on September 25, 1980.

Witnesses:	R.	Orton
	G.	Wagoner
		Huntsman
	Α.	Hanley

Office of County	Surveyor	County of	Umatilla
State of. Oregon	I berehv certify	that the within instrum	ant was filed in this office
for record on the	sumlen b		hatto DEPUTY

Form R6-7100-57 (9/71)

\$ GPO-798-276