CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

No corner was originally set.

DIAG	RAM	
T5N	R38E	
- 1	$S\frac{1}{16}$	
ł	S9	

Description of corner evidence found:

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 1"x30" Galvanized Pipe with 3" brass cap stamped:

From which:

A White Fir 14" dia. bears N60 $^{\rm O}E$ 61.8 ft., scribed: S 1/16 S9 BT.

A White Fir 7" dia. bears $S26^{\circ}E$ 64.9 ft., scribed S 1/16 S9 BT.

Attached 54-3 and 54-4 signs to both BTs. Attached brass washer stamped LS 1294 to foot blaze of both BTs. Painted blazes and 6" band around both BTs red.



CROWN ZELLER8 T5N R38E S1 16 S9 0R PLS 1294

I hereby certify the above corner monument was established as herein described on September 26, 1980.

Witnesses: R. Orton G. Wagoner L. Huntsman A. Hanley

Office of County Surveyor	County of Umatilla
State of Oregon / hereby certi	fu that the within instrument was filled in this offi
for record on the day of dearm	Bitte Shatt
(COUNTY OFFICIAL)	Dy DEPUTY

Form R6-7100-57 (9/71)

\$ GPO-798-276