CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None

Index No. U-1		

W.M.

: GPO 796-333

1

No record of subsequent remonumentation found in County Records . Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner

At the corner position a 2 inch by 30 inch iron pipe, with brass cap marked as shown, was set10 inches in the ground and surrounded with a mound of stones to the cap.

Set steel fence posts North, South, East, and West of corner on property line and attached signs 54-2 and 54-9.

Established 2 new BT's: A 101" red fir bears N86°W 45.8 ft. scribed S 1/16 S 25 BT.

A 102" red fir bears N65°E 11.8 ft. scribed 5 1/16 S 30 BT.

New BT's have lower blaze scribed BT with a brass washer stamped PLS 1106 nailed to it.

New BT's have 54-3 and 54-4 signs attached and a 6" red band painted around them above blaze.

Used steel tape and magnetic compass with 19¹/₂° east declination. Measured to center of Bts. See map of survey

This corner set August 13, 1979	PROFESSIONAL LAND SURVEYOR	T55 Stic
Witnesses: Greg Flowers, L.S.I.T.	Willia R. Wells	R30E R31E 925 830
Brent Reynolds	OREGON JULY 22, 1977 WILLIAM R. WELLS 1106	1979 PLS1106
Office of County Surveyor State of Oregon , I hereby certif	County of Umatilla	is office
for record on the day of	· · · ·	
(COUNTY OFFICIAL)	by	

RECEIVED BY

Umatilla County Surveyor Date <u>Sept 4, 1979</u> Rec'd By <u>M. Kughts</u> No. <u>G -1164-B</u>

Form R6-7100-57 (9/71)