	X-2	-5
History of original corner establishment: Corner established in 1880	DIAGRAM	
by George S. Pershin, under Contract No. 373.	T. 55.	
Surveyor General Record States:	RSOE	916
Set a basalt stone 20x14x8 on slight NW slope for ½ sec. cor.:	\$36	\$31
A pine 22 in. in diam. brs. East 68 lks. dist. A pine 36 in. in diam. brs. S. 48° W. 58 lks. dist.	•	1.1

No record of subsequent remonumentation found in County Records. Description of corner evidence found:

I did not find the original $\frac{1}{2}$ corner stone. I establish this corner at record bearing and distance from the one remaining BT. From the corner point:

A 40" pine bears S. 48° W. 38.3 ft. mkd. ½ S BT, in blaze that has been opened years ago.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the corner points: Set a 25"x30" galvanized iron nine 14" in the ground marked as shown: From which I scribe one NEW BEARING TREE:

A 20" pine bears S. 70° E. 141.6 ft. mkd. T5S R31E ½ S31 BT.

I nailed a brass washer marked "OPLS 598" to the BT blaze of this tree. Set a steel fence post 5 ft. N. of corner. Raised a mound of stone, 3 ft. base to top of pipe. Corner is at the SE corner of a stock water pond. Used a compass with 20° E. variation and steel tape, measuring to center of BTs.

REGISTERED PROFESSIONAL LAND SURVEYOR

REGON RT D BAGETT ROBERT

30,1976



for record on the...... day of..... 19.....

COUNTY OFFICIAL

(DEPUTY)

Form R6-7100-57 (9/71)

\$ OPO--- 798-276

I-142