USDA-FOREST SERVICE		/		
Index File No. <u>A-19</u>	CORNER (	RECORD (SEARCH) Ref. FSM 7151.4)	Tract or Survey No	No
T <u>5<b>% S</b></u> R. <u>32E</u>	R.D. <u>Ukiah</u>	County _		
Merid. Willamette	N.F. <u>Umatilla</u>	State	Oregon	
CORNER DIAGRAM	DESCRIBE CORNER	MONUMENT FOUND		<u> </u>
	Material: N	Mound of stone	Size: 4' x 6' x	1'
Sec	Markings: (	Original stone r	ot visible.	·
7	DESCRIBE BEARING	TREES OR OTHER OFF	ICIAL ACCESSORIES FOL	IND 2
	south of mou	ınd	ster on fence (19	47) corner 23'
•	Fence west a	and southeast/so	outh slope	'
PHOTO IDENTIFICATION DATA				
Photo No.				·
Filed At.				3
Object Ident.	DESCRIBE CORNER	LOCATION RELATIVE T	O NEAR-BY FEATURES, A	LSO HOW TO REACH CORNER
Ident. By				
Signature	<u>, 7</u>			
PLANE COORDINATE POSITION DA	TA			
State Zone				
x	{			
Υ	[			
Estab. By				
Signature	Title	División Heo	•	ote 7100-52 (3/68)
	re, Engr. Tech.		5-24	<del>1</del> -78

	GFO \$02 070			
MONUMENT: DESCRIBE NEW	MONUMENT SET, OR WORK DONE TO	PRESERVE EXIST	NG MONUMENT	
•				
				9
ACCESSORIES DESCRIBE N	EW BT's WITNESS OBJECTS ETC. EST	ABLISHED, OR WO	RK DONE TO PRESERVE EXISTING	EVIDENCE
				* • •
				-
				10
Work Done By	Title	Date	State Registration No.	
Certified Cor. Record Prepar			Date	 
	REMAR	RKS	<del></del>	
			•	

Tract or Surv. No.

Index File No.

T.

R.

M.

GPO 902-673

Cor.