OREGON CORNER RESTORATION FORM

Section:	28, 29, 32 & 33					
Township:	6 North					
Range:	34 East of the Willamette Meridian					
County:	Umatilla					
Date:	June 1, 2002					
Corner Indexing Information:		Township 6N	Range 34E	Corner Code	V 9	(Willamette Meridian)

Additional Identifier: (e.g. BLM designation for the corner, street intersection, plat name, block, lot, etc.)

This corner is common to sections 28, 29, 32 & 33.

Oregon Plane Coordinates: N: 842504.686 E: 8690483.510

Zone: North Order: second Datum: NAD83-91 Convergence: 1º21'43.3" Scale Factor: .99994714 Previous Renewals/Surveys, etc.: This corner was originally set by U.S. Deputy Surveyors William Odell and William Lewis under their contract No. 110 dated February 7, 1865. The Surveyor Generals notes state "set post corner, drove charred stake, dug pits and raised mounds per instructions". Krumbein, in 1982, shows a 2" pipe of unknown origin at the corner (Survey 82-46-B).

Monument(s) & Accessories Found (Condition & Source):

At the southwest corner of section 28, T6N R34E, found a 2"x54" iron pipe at the surface in east-west fence line.

Monument Set (Procedures & Description):

Monument Detail:



NEW ACCESSORIES: WE SET:

A 5/8 rebar with yellow plastic cap stamped 'Tomkins Surveying' which bears East ~ 13.05 feet A 5/8 rebar with yellow plastic cap stamped 'Tomkins Surveying' which bears East ~ 13.05 feet from the corner. Attached a Umatilla County Bearing Object Sign to Southwest face of the Locust Fence Post. A 5/8 rebar with yellow plastic cap stamped 'Tomkins Surveying' which bears South ~ 7.42 feet from the corner. No steel t-post set or a Umatilla County Bearing Object Sign A 5/8 rebar with yellow plastic cap stamped 'Tomkins Surveying' which bears West ~ 16.00 feet from the corner. Attached a Umatilla County Bearing Object Sign to Southeast face of the Locust Fence Post. A 5/8 rebar with yellow plastic cap stamped 'Tomkins Current of the Locust Fence Post. A 5/8 rebar with yellow plastic cap stamped 'Tomkins Surveying' which bears N 5°E ~ 6.87 feet from the corner. No steel t-post set or a Umatilla County Bearing Object Sign. Location & Comments:

Compass Declination:

19° East

Surveyor's Seal

Tomkins Land Surveying, Inc. Firm/Agency: 20 E. Poplar, Suite 204 Walla Walla, WA 99362 Party Chief: **Bryan Martin** Notes: **Bryan Martin**

Witness: Eric Flowers

REGISTERED PROFESSIONAL LAND SURVEYOR W OREGON JULY 26, 1988 PAUL W. P. TOMKINS 2360 renews 6/30/04

6/30/02

ORLCR6N34EV9.DOC

03-23- C