# **OREGON CORNER RESTORATION FORM**

COUNTY: Umatilla DATE: 02/17/2015

**CORNER DESIGNATION:** N-15, Quarter Corner for Sections 15 and 22, Township 6 North, Range 37E, W.M.

## PREVIOUS RENEWALS/SURVEYS ETC:

Originally surveyed by A. H. Simmons for US Deputy Surveyor George Williams under his contract No. 176 dated July 20, 1872. His notes state "Set stone 14 x 15 x 20 on steep side hill face W. for 1/4 Sec. Cor.

# **MOUNUMENT AND ACCESSORIES FOUND:**

No evidence found

### **MOUNUMENT MARKING DETAIL:**

LS 02820 T6N R37E 1/4 <u>S 15</u> S 22 2/2015

#### MOUNUMENT AND ACCESSORIES SET:

At the surveyed position, set 2<sup>1</sup>/<sub>2</sub> ins. brass cap on 1<sup>1</sup>/<sub>2</sub>" x 30" ins. galvanized iron pipe. 3 ins. above the ground stamped T 6N, R 37E, <sup>1</sup>/<sub>4</sub> S15, S 22, 2/2015 LS 02820, from which: An 18 ins. in diam., fir, bears N. 61° W., 40.30 ft., blazed, scribed and tagged. A 14 ins. in diam., fir, bears N. 58° E., 39.70 ft., blazed, scribed and tagged. Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears S. 44° E., 18.00 ft. Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears S. 54° W., 24.00 ft.

# LOCATION AND COMMENTS:

Bearings taken with Silva hand compass and distances measured with a steel tape.

OREGON STATE PLANE COORDINATE, North Zone, NAD 83(91), International Feet: N = 856112.27 E = 8793180.56

# COMPASS DECLINATION: 15° East

FIRM: HDJ Design Group 5 N. Colville, Suite 200 Walla Walla WA 99362

WITNESSES: Joseph R. Latimer Cory A. West

## SURVEYORS' SEAL:



15-063-C